

S-CARS.ORG
 18005 30th Ave N
 Plymouth, Minnesota 55447
 United States

6122936575
 s-cars.org/site

BILL TO
Darin Nederhoff
 Darin Nederhoff

6122936575
 editor@s-cars.org

Invoice Number: 170
P.O./S.O. Number: 2004 Audi A6 2.7T S-Line
Invoice Date: September 27, 2025
Payment Due: September 27, 2025
Amount Due (USD): \$1,366.31

Items	Quantity	Price	Amount
LABOR Remove and replace all front end control arms, tie-rod ends and struts and upper mounts. Remove and replace rear shocks and upper mounts. Replace crankshaft position sensor Tighten driver side heat shield to quiet rattle. Tech: Chris DeLadi	1	\$600.00	\$600.00
BOS-0261210217 Audi Crankshaft Sensor (FCP: R536270750)	1	\$38.19	\$38.19
R389439528 Vaico Audi Full Control Arm Kit (FCP: R389439528)	1	\$270.00	\$270.00
LEM-1766201 Audi Strut Mount, Front Upper. Lemforder (FCP: R389439528)	2	\$12.99	\$25.98
FEB-103101 Audi Shock Mount, Rear Upper, Febi (FCP: R389439528)	2	\$35.79	\$71.58
BIL-19293912 Bilstein B4 3B0513031R Rear Shock Absorber (FCP: R981554663)	2	\$89.00	\$178.00
KIT-8D0413031BNKT Audi Strut Kit - Bilstein B4 Touring, Front 8D0413031BNKT (FCP: R981554663)	1	\$182.56	\$182.56

INVOICE

S-CARS.ORG
18005 30th Ave N
Plymouth, Minnesota 55447
United States

6122936575
s-cars.org/site

Items	Quantity	Price	Amount
Note Four wheel alignment required at additional cost.	1	\$0.00	\$0.00

Total: \$1,366.31

Amount Due (USD): \$1,366.31

Notes / Terms

Mileage at service: 135,725 mi