

STATE FARM INSURANCE CO  
1665 W. ALAMEDA DRIVE TEMPE AZ 85289  
(602) 784-2000

FOR ANY QUESTIONS REGARDING THIS ESTIMATE PLEASE CONTACT THE  
INDICATED CLAIMS HANDLER

Damage Assessed By: Bryan Enos

Claims Handler: LYNDA OSBORN-JACKSON 784-2052

Type of Loss: Comprehensive (Spec)

Date of Loss: 10/11/95

Deductible: 250.00

Insured: CHRISTIAN HALLGREN

Address: 510 S EXTENTSION ROAD #3091 MESA AZ 85210-2255

Telephone: Work Phone: 406-3638

Home Phone: 649-7316

Mitchell Service: 913748

Description: 1991 TOYOTA MR2 2D CPE.

VIN: JT2SW22M7M0003527

License: FZW 822 AZ

Mileage: 85,287

DEM/ALT: A

Color: BLACK

Search Code: PHX

| Line Entry  | Labor                       | Line Item                           | Part Type/  | Dollar  | Labor |
|-------------|-----------------------------|-------------------------------------|-------------|---------|-------|
| Item Number | Type Operation              | Description                         | Part Number | Amount  | Unit  |
| 1           | 301060 BODY REPAIR          | *BUMPER/GRILLE COVER                |             |         | 3.0*  |
| 2           | AUTO REFIN REFINISH         | BUMPER/GRILLE COVER                 |             |         | 2.6   |
| 3           | 301850 BODY REPAIR          | *L RETRACTABLE H/LAMP HOUSING COVER |             |         | 0.5*  |
| 4           | AUTO REFIN REFINISH         | L LAMP COVER                        |             |         | 0.5   |
| 5           | 302760 BODY REPAIR          | *HOOD PANEL                         |             |         | 5.0*  |
| 6           | AUTO REFIN REFINISH         | HOOD OUTSIDE                        |             |         | 2.6   |
| 7           | 323120 BODY REPAIR          | *UPR LUGGAGE LID SPOILER            |             |         | 3.0*  |
| 8           | AUTO REFIN REFINISH         | UPR SPOILER                         |             |         | 1.0   |
|             |                             | INCLS R&I                           |             |         |       |
| 10          | 933005 BODY ADD'L LABOR OPR | RESTORE CORROSION PROTECTION        |             | 5.00*   | 0.3*  |
| 11          | 936013 ADD'L COST           | SPCL PAINT MATERIALS                |             | 7.50*   |       |
| 12          | AUTO ADD'L COST             | PAINT MATERIALS                     |             |         |       |
|             |                             |                                     |             | 134.00* |       |

\* Judgement Item

Remarks

DOP 11/90

|                      | Units | Rate  | Add'l Labor Amount | Sublet Amount | Totals |
|----------------------|-------|-------|--------------------|---------------|--------|
| I. Labor Subtotals   |       |       |                    |               |        |
| Body                 | 11.8  | 32.00 | 5.00               |               | 382.60 |
| Refinish             | 6.7   | 32.00 |                    |               | 214.40 |
| Labor Summary Totals | 18.5  |       |                    |               | 597.00 |

|                                 |        |
|---------------------------------|--------|
| II. Part Replacement Summary    | Amount |
| Total Replacement Parts Amount: | 0.00   |

ESTIMATE RECALL NUMBER: 10/17/95 15:19:04 03-1646-60401

Mitchell Data Version: OCT\_95\_A

Copyright (C) 1990, Mitchell International  
All Rights Reserved



Date: 10/17/95 03:19 P.M.  
Estimate ID: 03-1646-60401  
Committed  
Profile ID: 32.0



THIS IS NOT AN AUTHORIZATION TO REPAIR.  
ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL  
BY A STATE FARM CLAIM REPRESENTATIVE.



THIS IS NOT AN AUTHORIZATION TO REPAIR.  
ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL  
BY A STATE FARM CLAIM REPRESENTATIVE.



THIS IS NOT AN AUTHORIZATION TO REPAIR.  
ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL  
BY A STATE FARM CLAIM REPRESENTATIVE.

|                         |        |                              |         |
|-------------------------|--------|------------------------------|---------|
| III. Additional Costs   | Amount | IV. Adjustments              | Amount  |
| Taxable Costs           | 141.50 | Insurance Deductible         | 250.00- |
| Sales Tax @ 6.95%       | 9.83   | Customer Responsibility:     | 250.00- |
| Total Additional Costs: | 151.33 |                              |         |
|                         |        | I. Total Labor:              | 597.00  |
|                         |        | II. Total Replacement Parts: | 0.00    |
|                         |        | III. Total Additional Costs: | 151.33  |
|                         |        | Gross Total:                 | 748.33  |
|                         |        | IV. Total Adjustments:       | 250.00- |
|                         |        | Net Total:                   | 498.33  |

Point of Impact: 16 NON COLLISION  
Body Shop: unk

Inspection Site: TSC

**\*\*CAUTION\*\***

NOTICE: REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING  
EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER.