

S-CARS.ORG

18005 30th Ave N
Plymouth, Minnesota 55447
United States6122936575
s-cars.org/site

BILL TO

Darin Nederhoff
Darin Nederhoff6122936575
editor@s-cars.org**Invoice Number:** 192**P.O./S.O. Number:** 2003 Audi S8**Invoice Date:** August 23, 2026**Payment Due:** August 23, 2026**Amount Due (USD):** \$557.16

Items	Quantity	Price	Amount
LABOR Remove passenger valve cover, replace camshaft tensioner seal at rear, rear cam cap, half-moon seal, apply sealant to cam bridge and reassemble. Remove front bumper. Perform repair to passenger lower side bumper due to poor bodyshop repair. Reinstall aluminum trim under headlight OE Audi mounting hardware. Replace passenger side rear suspension coil spring. Replace passenger rear sway bar link due to original being seized. Tech: Chris DeLadi & Darin Nederhoff	1	\$240.00	\$240.00
USED Used OE Audi rear coil spring sourced from D2 S8 owner (Riley) in Duluth.	1	\$60.00	\$60.00
KIT Audi OE Lower Headlight Mounting Clips Kit (both sides) sourced from Rich in Texas	1	\$200.00	\$200.00
215870 Elring Audi VW Engine Camshaft Plug	2	\$6.99	\$13.98
Note FCP Order: R473236228 July 22, 2026 for Elring part above	1	\$0.00	\$0.00

S-CARS.ORG18005 30th Ave N
Plymouth, Minnesota 55447
United States6122936575
s-cars.org/site

Items	Quantity	Price	Amount
077 198 217 Camshaft Tensioner Gasket Set (includes half moon) OE Audi	1	\$30.78	\$30.78
JTS122 TRW Rear Sway Bar Link - 4D0505465D (RokAuto Order 226631191 - Dec 29, 2022 stock)	1	\$12.40	\$12.40
Total:			\$557.16
Amount Due (USD):			\$557.16

Notes / Terms

Mileage at service: 165,085 mi.