

S-CARS.ORG
 18005 30th Ave N
 Plymouth, Minnesota 55447
 United States

6122936575
 s-cars.org/site

BILL TO
Darin Nederhoff
 Darin Nederhoff

6122936575
 editor@s-cars.org

Invoice Number: 182
P.O./S.O. Number: 2004 Audi A6 2.7T S-Line
Invoice Date: April 23, 2026
Payment Due: April 23, 2026
Amount Due (USD): \$1,314.26

Items	Quantity	Price	Amount
LABOR PCV Breather tubes showing signs of freezing, excessive smoking from exhaust. Remove Y pipe and remove existing breather tube and clean out. Remove lower intercooler hoses and drain oil from them. Remove intake manifold and fuel rail to replace leaking after-run coolant pump. Install new intake manifold gaskets, injector seals etc. Tech: Chris DeLadi	1	\$150.00	\$150.00
LABOR Replace coolant overflow tank and cap	0.4	\$80.00	\$32.00
FEB-30845 Febi Coolant Expansion Tank for Audi A6 2.7T	1	\$16.50	\$16.50
FEB-40723 Febi Coolant Expansion Tank Cap for Audi A6 2.7T	1	\$9.89	\$9.89
Note Coolant Tank and Cap from FCP Euro Order #R056310413 for warranty purposes. Purchased 2026 - Sun Feb, 8	1	\$0.00	\$0.00
LABOR Perform oil change with filter	0.2	\$80.00	\$16.00

S-CARS.ORG
 18005 30th Ave N
 Plymouth, Minnesota 55447
 United States

6122936575
 s-cars.org/site

Items	Quantity	Price	Amount
QS5W40E Quaker State 5W40 European Synthetic Motor Oil, 7.3 QT fill (5 qt bottles)	2	\$23.00	\$46.00
H24W04 Hengst Oil Filter for Audi 2.7T V6 (078115561J)	1	\$13.29	\$13.29
078 965 561 Aux Water Pump ES#2710	1	\$82.99	\$82.99
078 129 717 NKT2 Intake Manifold Installation Kit (Audi 2.7T) Included in this kit: Throttle body gasket Intake manifold gasket Intake manifold hardware Fuel rail hardware Fuel Injector seals Fuel Injector clips	1	\$121.31	\$121.31
078 121 082H Auxiliary Water Pump Hose ES#3234886 Connects the water pipe to the auxiliary water pump	1	\$26.99	\$26.99
058 133 843 Audi A6 2.7 Air Filter (Hengst)	1	\$13.48	\$13.48
034-108-3010 Silicone Air Intake Duct / MAF Hose ES#2864564 Larger inside diameter and smoother surface for better flow, and stiffer construction to prevent collapsing	1	\$115.00	\$115.00
Note 5 items above from ECS Order #: 162-349-259 3/22/26	1	\$0.00	\$0.00

S-CARS.ORG
 18005 30th Ave N
 Plymouth, Minnesota 55447
 United States

6122936575
 s-cars.org/site

Items	Quantity	Price	Amount
KAY-3007625A00 Audi Vacuum Check Valve (FCP Order R891407439)	1	\$15.19	\$15.19
VAI-V103696 Audi Secondary Air Injection Hose (FCP Order R891407439)	1	\$99.95	\$99.95
VAI-V103695 Audi Crankcase Breather Hose (2.7T Spider Hose). (FCP Order R818302576)	1	\$434.99	\$434.99
CRP-N90316802 Audi Coolant Temp Sensor O-Ring (FCP Order R056310413)	1	\$0.99	\$0.99
FEB-12408 Coolant Temp Sensor Retaining Clip (FCP Order R056310413)	1	\$1.09	\$1.09
207-456-273 Engine Coolant Temperature Sensor (Green) 059919501AKT2 (ECS Order 207-456-273. 12/28/25)	1	\$45.37	\$45.37
TAXPAID Taxes Paid on Parts Orders ECS \$15.68 ECS \$26.27 FCP \$17.04 FCP \$4.43 FCP \$9.81	1	\$73.23	\$73.23

Total:	\$1,314.26
Amount Due (USD):	\$1,314.26

S-CARS.ORG
18005 30th Ave N
Plymouth, Minnesota 55447
United States

6122936575
s-cars.org/site

Notes / Terms

Mileage at service: 138,975 mi.