

Theft Records

0 | Theft Records Found

Title Records

1 | Title Record Found

Source: NMVTIS

Title 1

Title Issue Date	State	Status	Mileage (M)	VIN
07/28/2015	AZ	Current	142921	JT2SW22M7M0003527
02/14/2006	AZ	Historical	142921	JT2SW22M7M0003527
01/12/2000	OH	Historical	27158	JT2SW22M7M0003527
11/15/1994	AZ	Historical	65714	JT2SW22M7M0003527

Title Brands

1 | Title Brand Found

Source: NMVTIS

Brand	Date Applied	Reported by	Type
! Exceeds Mechanical Limits	01/12/2000	OHIO	State

The following are all possible brands applied on this vehicle

✓ Clear	✓ Warranty Return	✓ Manufacturer Buy Back
✓ Flood damage	✓ Antique	✓ Former Rental
✓ Fire damage	✓ Classic	✓ Salvage--Stolen
✓ Hail damage	✓ Agricultural Vehicle	✓ Salvage--Reasons Other Than Damage or Stolen
✓ Salt water damage	✓ Logging Vehicle	✓ Disclosed Damage
✓ Vandalism	✓ Street Rod	✓ Prior Non-Repairable / Repaired
✓ Kit	✓ Vehicle Contains Reissued VIN	✓ Crushed
✓ Dismantled	✓ Replica	✓ Inoperable Vehicle
✓ Junk	✓ Totaled	✓ Hazardous Substance Contaminated Vehicle
✓ Rebuilt	✓ Owner Retained	✓ Export Only Vehicle
✓ Reconstructed	✓ Reserved	✓ Actual

✓ Salvage--Damage or Not Specified	✓ Memorandum Copy	✓ Not Actual
✓ Test Vehicle	✓ Reserved	✓ Not Actual - Odometer tampering verified
✓ Refurbished	✓ Recovered Theft	✓ Exempt from Odometer Disclosure
✓ Collision	✓ Undisclosed Lien	! Exceeds Mechanical Limits
✓ Reserved	✓ Prior Owner Retained	✓ Odometer may be Altered
✓ Salvage Retention	✓ Vehicle Non-conformity Uncorrected	✓ Odometer Replaced
✓ Prior Taxi	✓ Vehicle Non-conformity Corrected	✓ Reading at Time of Renewal
✓ Prior Police	✓ Vehicle Safety Defect Uncorrected	✓ Odometer Discrepancy
✓ Original Taxi	✓ Vehicle Safety Defect Corrected	✓ Call Title Division
✓ Original Police	✓ VIN replaced by a new state assigned VIN	✓ Rectify Previous Exceeds Mechanical Limits Brand
✓ Re-manufactured	✓ Gray Market	✓ Pending Junk Automobile
✓ Reserved	✓ Gray Market	✓ Junk Automobile

Open Recalls

0 | Open Recalls Found

Other Recalls

1 | Other Recalls Found

Components: AIR Bags

Report Receipt Date: 12/24/1991

NHTSA Campaign: 91v223000

Summary: THE Driver's Occupant Protection System (Steering Wheel and AIR Bag) Exceeds THE 60G Thorax Criterion IN Nhtsa Crash Tests.

Consequence: THE Occupant Protection System Does NOT Comply With Theenergy Absorption Requirements OF Fmvss 208. This Reduces THE Crash Protectionafforded BY THE Steering Wheel and AIR BAG Systems IN Event OF AN Accident.

Remedy: Replace THE Steering Wheel With A Modified Wheel Designed FOR Increased Energy Absorption.

Notes: System: Steering Wheel and AIR Bag; Fmvss 208.vehicle Description: Passenger Vehicles.

Market Value Range

3 | Market Values Found

#	Name	Value
---	------	-------

1	Above Market	\$31,452
2	Market Average	\$24,257
3	Below Market	\$17,062

Ownership Costs

0 | Ownership Costs Found

Equipment

35 | Equipments Found

#	Group	Name	Value	Availability
1	Anti-Theft & Locks	Power Door Locks		Optional
2	Braking & Traction	ABS Brakes		Optional
3	Safety	Driver Airbag		Standard
4	Climate Control	Air Conditioning		Optional
5	Interior Features	Cruise Control		Optional
6	Interior Features	Tachometer		Standard
7	Entertainment, Communication & Navigation	Cassette Player		Standard
8	Seat	Leather Seat		Optional
9	Roof	Manual Sunroof		Optional
10	Tires & Wheels	Alloy Wheels		Standard
11	Mirrors & Windows & Wipers	Power Windows		Optional
12	Mirrors & Windows & Wipers	Rear Window Defogger		Standard
13	Chassis	Anti-Brake System	Non-Abs 4-Wheel ABS	
14	Chassis	Steering Type	R&P	
15	Chassis	Front Brake Type	Disc	
16	Chassis	Rear Brake Type	Disc	
17	Chassis	Front Suspension	IND	
18	Chassis	Rear Suspension	IND	
19	Chassis	Front Spring Type	Coil	
20	Chassis	Rear Spring Type	Coil	
21	Chassis	Tires	195/60r14	
22	Interior Dimensions	Front Headroom	37.50 In.	
23	Interior Dimensions	Front Legroom	43.40 In.	
24	Interior Dimensions	Front Shoulder Room	54.00 In.	
25	Interior Dimensions	Front Hip Room	52.20 In.	
26	Exterior Dimensions & Weight	Curb Weight-manual	2758 Lbs	
27	Exterior Dimensions & Weight	Overall Length	164.20 In.	

28	Exterior Dimensions & Weight	Overall Width	66.90 In.
29	Exterior Dimensions & Weight	Overall Height	48.80 In.
30	Exterior Dimensions & Weight	Wheelbase	94.50 In.
31	Exterior Dimensions & Weight	Track Front	57.90 In.
32	Exterior Dimensions & Weight	Track Rear	57.10 In.
33	Cargo Bed Dimensions	Overall Length	164.20 In.
34	Capacities	Standard Seating	2
35	Color	Super White	Exterior

Warranties

0 | Warranties Found

Disclaimer: This report does not contain detailed information regarding a vehicle's repair history nor information on all motor vehicles in the United States because some states are not yet providing their vehicle data to the system. Currently, the data provided by states is provided in a variety of time frames; while some states report and update data in "real-time" (as title transactions occur), other states send updates less frequently. Owner information may not be fully updated or accurate in all instances.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company to be a "total loss" or branded by a state titling agency.

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, users are strongly encouraged to also obtain an independent vehicle inspection to ensure the vehicle does not have hidden damage.

It may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time.

Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.

The information used to compile this report is aggregated from various government agencies, non-profit organizations, and industry sources. The accuracy and reliability of the information supplied depends primarily on the reporting sources, and all entities involved in compiling this report accept no liability for any errors or omissions.



NMVTIS Disclaimer: The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMVTIS is intended to serve as a reliable source of title and **brand** history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because **some states** are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, consumers are **strongly encouraged to also obtain an independent vehicle inspection** to ensure the vehicle does not have hidden damage. The **Approved NMVTIS Data Providers** (look for the NMVTIS logo) can include vehicle condition data from sources other than NMVTIS.

Consumer Access Product Disclaimer